



# GS2970/GS2971 Errata

Fill out a technical support request at [http://www.gennum.com/support/tech\\_inquiry.php](http://www.gennum.com/support/tech_inquiry.php) to receive FPGA work-around code where available as described below:

## 1. Audio channels 3~8 output misaligned to WCLK for SD formats

Devices Affected: GS2970 & GS2971.

Workaround Available: Yes. The workaround can be implemented in an FPGA. The workaround requires FPGA logic resources, connectivity to affected products (GSPI interface and other signals).

Impact: If using serial audio and the condition occurs (CH3-8 are not aligned to the WCLK), the output audio will be corrupt. AES/EBU has embedded clock information, so the condition can still happen, but the output audio will not be corrupted.

Summary: Under certain conditions, audio channels 3-8 get misaligned with the WCLK, hence leading to corrupted audio for applications using serial audio.

Detailed Description:

This is a problem with I<sup>2</sup>S and serial audio output modes by corrupting the audio data only, and does not corrupt AES/EBU audio data in AES mode.

The audio at AOUT1/2 will always be aligned to WCLK output.

Audio outputs AOUT3/4, AOUT5/6 and AOUT7/8 may be misaligned, as shown in Figure 1-1:




Figure 1-1: Audio Channel Misalignment

The problem occurs randomly after the device has locked or re-locked to the video source. Sometimes all channels will be aligned to WCLK and sometimes not.

This problem occurs due to an internal audio word clock offset for audio outputs 3 through 8 caused by misdetection of the audio 5-frame sequence. The device only has one WCLK output taken from the source of AOUT1/2. The system is unable to detect the misalignment of audio outputs 3 through 8 since their respective word clocks are not provided external to the device.

Since AOUT1/2 is always aligned to the WCLK output, the first two channels of audio from the selected primary audio group will always be aligned to WCLK. By default, audio channels 1 and 2 from embedded audio Group 1 (primary audio group) will always be aligned to WCLK. If embedded audio Group 2 is set as the primary audio group, audio channels 5 and 6 will always be aligned to WCLK. See Figure 1-2 below. The primary audio group is selected using the IDA[1:0] bits in register 400h.




Figure 1-2: Audio Group 2 Selected as Primary Audio Group

Genum will provide FPGA IP code as a workaround for this bug.

## 2. Audio channel offset within audio channel pair for SD formats

Devices Affected: GS2970 & GS2971.

Workaround Available: Currently, no workaround is available.

Impact: Audio is not corrupted.

Summary: Under certain conditions, one audio channel in a pair might get misaligned relative to the other channel within the pair.

Detailed Description:

This is a problem in I<sup>2</sup>S mode, serial audio modes, as well as AES mode.

This problem will only occur when the device is de-embedding audio from an SD video source. The problem occurs randomly after the device has locked or re-locked to the video source (SDI input source is repeatedly plugged and un-plugged).

Within an audio channel pair, one of the channels (left or right for stereo) may be offset by one WCLK with respect to the samples original position. This is illustrated in Figure 2-1 below.




Figure 2-1: Audio Channel Offset

This offset can occur in any of the channel pair outputs, AOUT1/2, AOUT3/4, AOUT5/6 or AOUT7/8, and in any of the audio output modes, including AES. The offset can also occur with the first or second channel within an audio channel pair. The problem occurs randomly after the device has locked or re-locked to the video source.

Currently, no workaround is available for this issue.

### 3. Erroneous audio outputs when Audio Group removed from HD or 3G source

Devices Affected: GS2970 & GS2971.

Workaround Available: Yes. The workaround is a set of recommendations for action by equipment firmware, and small circuit implementation in FPGA.

Impact: Audio gets corrupted if condition occurs.

Summary: When there is no embedded audio in one of the groups, the device outputs invalid data on the channels within that audio group.

Detailed Description:

This is a problem in I<sup>2</sup>S mode, serial audio modes, as well as AES mode.

This problem only affects the device when operating with HD or 3G formats.

When the device is de-embedding two audio groups from an HD or 3G source, if one or both of the embedded audio groups are no longer present in the input, the corresponding audio outputs (by default, AOUT1/2 and AOUT3/4 for Group 1 or AOUT5/6 and AOUT7/8 for Group 2) may sometimes output erroneous data.

In this scenario, the audio mute functions (via host interface register 200h for MUTE\_ALL or register 205h for MUTEA/B) do not function, and erroneous data continues to be output, even when an output has been set to mute.

The user can check the audio group detect bits (ADPGx\_DET, bits 4:1) in register 202h of the host interface to check when the audio group is no longer present. If one of the embedded audio groups is no longer present, the corresponding audio outputs should be ignored by the system. Since the workaround involves mostly polling the register above, there is no need for Gennum to provide any FPGA IP workaround for this bug.

The mute function works correctly when the device is extracting audio from both audio groups.

## 4. WCLK (and other audio clocks) output frequency variation when plugging and un-plugging SDI input

Devices Affected: GS2970 & GS2971.

Workaround Available: Yes. The workaround can be implemented in an FPGA. The workaround requires FPGA logic resources, connectivity to affected products (GSPI interface and other signals).

Impact: Audio gets corrupted if condition occurs. Recommend implementation of FPGA IP workaround.

Summary: Under certain conditions, WCLK can vary slightly from 48kHz (47kHz to 49kHz).

### Detailed Description:

This is a problem in I<sup>2</sup>S mode, serial audio modes, as well as AES mode.

This problem occurs for all SD, HD and 3G formats.

When the SDI input source is repeatedly plugged and un-plugged, the WCLK output timing may not always be correctly set to 48kHz. The variation occurs randomly, and can be between 47kHz and 49kHz. When this variation happens in WCLK, the variation is also observed in AMCLK and ACLK, since these two clocks are derived from the same clock generator base as the WCLK.

When the device unlocks and then re-locks to the SDI signal, the internal audio timing generator must be reset via the host interface. To reset the audio timing generator, write 0x004 into reserved register 05Eh to set the Audio Clock Gen bit 2, and then write 0x000 to address 05Eh to bring it back out of reset.

The system may monitor the locked status of the device via the LOCKED output signal (default STAT3 ball B6), or via the STD\_LOCK bit 12 in host interface register 022h.

Gennum will provide a workaround for this bug in the form of FPGA IP and instructions on programming the GS2970/GS2971 registers as outlined above.

## 5. Video line number error flag stuck HIGH when HD/3G input format changes

Devices Affected: GS2960 & GS2961; GS2970 & GS2971

Workaround Available: Yes. The workaround is a set of recommendations for action by equipment firmware, and requires GSPI connectivity with the device.

Impact: Video is not impacted. This affects only the line number monitoring function.

Summary: The Line Number Error flag might be set HIGH, even though there are no line number errors.

### Detailed Description:

This problem occurs when the HD or 3G input format changes (for example: when the input HD source changes between 1080i and 720p, or when the 3G source changes between 1080p60 and 1080p59.94).

When the HD/3G input format changes, the line number error flag may be set to denote a line number error (LNUM\_ERR bit 2 in register 002h set HIGH). In this case, one of two things may have occurred:

1. The error flag is set HIGH, even though there is no line number error in the input source.
2. The error flag is set HIGH, the device is programmed to insert line numbers (enabled by default), and the device may have inserted incorrect video line numbers.

Even though the error flag register 002h is “clear on write”, writing all ones to this register will not clear the LNUM\_ERR flag as expected.

There are two possible ways to clear the line number error flag:

1. Reset the device.
2. Toggle reserved bit 13 HIGH then LOW in register 000h.

If the system is not using the line number error reporting function, the system can mask this error flag by setting the ERROR\_MASK bit 2 HIGH in register 037h.

If the system is not using the line number insertion function, the system can disable this permanently by setting the LNUM\_INS\_MASK bit 1 HIGH in register 000h.

## 6. Chroma channel ancillary data checksum error flag stuck HIGH when switching from HD/3G to SD formats or from HD/3G to HD/3G formats with no CANC data

Devices Affected: GS2960 & GS2961; GS2970 & GS2971.

Workaround Available: Yes. The workaround is a set of recommendations for action by equipment firmware, and requires GSPI connectivity with the device.

Impact: Video is not impacted. This affects only the CANC checksum monitoring function.

Summary: The CANC checksum error flag might be set HIGH after switching input formats, even though the flag might be irrelevant.

### Detailed Description:

This problem occurs when switching from any HD/3G input format to any SD format. It also occurs when switching from any HD/3G input format to any HD/3G format with no ancillary data in the Chroma video data stream (CANC).

When the HD/3G input changes to SD or HD/3G input (with no CANC data), the Chroma channel checksum error flag may be set to denote a checksum error (CCS\_ERR bit 6 in register 002h set HIGH). The error flag is set HIGH during the format switch and continues to be set HIGH because the flag is only cleared when new CANC data is present.

Even though the error flag register 002h is “clear on write”, writing all ones to this register will not clear the CCS\_ERR flag as expected. The flag can be cleared by resetting the device.

Since the CCS\_ERR error flag is not applicable in SD mode, the user can mask this bit when they switch to an SD format by setting the CCS\_ERR bit 6 HIGH in the ERROR\_MASK register 037h.

For HD/3G mode, the user can monitor the Chroma ancillary data via the C/2ANC signal on one of the STAT output pins. This pin is HIGH whenever ANC data is detected in the Chroma data stream, and LOW when no ANC data is detected. If this output stays LOW, there is no ancillary data in the Chroma stream and the CCS\_ERR bit can be ignored by masking the CCS\_ERR bit in the ERROR\_MASK register 037h. If there is ancillary data present on the Chroma stream then the CCS\_ERR flag that is stuck will be cleared once the next CANC data is detected by the device.

## 7. Luma channel ancillary data checksum error flag stuck HIGH when switching from SD/HD/3G to SD/HD/3G formats with no YANC data

Devices Affected: GS2960 & GS2961; GS2970 & GS2971.

Workaround Available: Yes. The workaround is a set of recommendations for action by equipment firmware, and requires GSPI connectivity with the device.

Impact: Video is not impacted. This affects only the YANC checksum monitoring function.

Summary: The YANC checksum error flag might be set HIGH after switching input formats, even though flag might be irrelevant.

### Detailed Description:

This problem occurs when switching from any SD/HD/3G input format to any SD/HD/3G format with no ancillary data in the Luma video data stream (YANC). If YANC packets are present in the input video, this problem will not occur.

When the format change occurs, the Luma channel checksum error flag may be set to denote a checksum error (YCS\_ERR bit 5 in register 002h set HIGH). The error flag is set HIGH during the format switch, and continues to be set HIGH because the flag is only cleared when new YANC data is present.

Even though the error flag register 002h is “clear on write”, writing all ones to this register will not clear the YCS\_ERR flag as expected. The flag can be cleared by resetting the device.

The system can monitor the Luma ancillary data status via the Y/1ANC signal on one of the STAT output pins (default STAT4 ball C5). This output is HIGH whenever ANC data is detected in the Luma data stream, and LOW when no ancillary data is detected. If this bit stays LOW, there is no YANC data in the Luma stream and the YCS\_ERR bit can be ignored by masking the YCS\_ERR bit in the ERROR\_MASK register 037h. If there is ancillary data present on the Luma stream then the YCS\_ERR flag that is stuck will be cleared once the next YANC data is detected by the device.

## Revision History

Version	ECR	Date	Changes
3	153147	November 2009	Updates.
2	152588	September 2009	Updates.
1	152489	August 2009	Updates.
0	152266	July 2009	New document.

### DOCUMENT IDENTIFICATION INFORMATION NOTE

Information relating to this product and the application or design described herein is believed to be reliable, however such information is provided as a guide only and Gennum assumes no liability for any errors in this document, or for the application or design described herein. Gennum reserves the right to make changes to the product or this document at any time without notice.

### CAUTION

ELECTROSTATIC SENSITIVE DEVICES  
DO NOT OPEN PACKAGES OR HANDLE EXCEPT AT A  
STATIC-FREE WORKSTATION



### GENNUM CORPORATE HEADQUARTERS

4281 Harvester Road, Burlington, Ontario L7L 5M4 Canada

Phone: +1 (905) 632-2996

E-mail: [corporate@gennum.com](mailto:corporate@gennum.com)

Fax: +1 (905) 632-2055

[www.gennum.com](http://www.gennum.com)

### OTTAWA

232 Herzberg Road, Suite 101  
Kanata, Ontario K2K 2A1  
Canada

Phone: +1 (613) 270-0458

Fax: +1 (613) 270-0429

### CALGARY

3553 - 31st St. N.W., Suite 210  
Calgary, Alberta T2L 2K7  
Canada

Phone: +1 (403) 284-2672

### UNITED KINGDOM

North Building, Walden Court  
Parsonage Lane,  
Bishop's Stortford Hertfordshire, CM23 5DB  
United Kingdom

Phone: +44 1279 714170

Fax: +44 1279 714171

### INDIA

#208(A), Nirmala Plaza,  
Airport Road, Forest Park Square  
Bhubaneswar 751009  
India

Phone: +91 (674) 653-4815

Fax: +91 (674) 259-5733

### SNOWBUSH IP - A DIVISION OF GENNUM

439 University Ave. Suite 1700  
Toronto, Ontario M5G 1Y8  
Canada

Phone: +1 (416) 925-5643

Fax: +1 (416) 925-0581

E-mail: [sales@snowbush.com](mailto:sales@snowbush.com)

Web Site: <http://www.snowbush.com>

### MEXICO

288-A Paseo de Maravillas  
Jesus Ma., Aguascalientes  
Mexico 20900

Phone: +1 (416) 848-0328

### JAPAN KK

Shinjuku Green Tower Building 27F  
6-14-1, Nishi Shinjuku  
Shinjuku-ku, Tokyo, 160-0023  
Japan

Phone: +81 (03) 3349-5501

Fax: +81 (03) 3349-5505

E-mail: [gennum-japan@gennum.com](mailto:gennum-japan@gennum.com)

Web Site: <http://www.gennum.co.jp>

### TAIWAN

6F-4, No.51, Sec.2, Keelung Rd.  
Sinyi District, Taipei City 11502  
Taiwan R.O.C.

Phone: (886) 2-8732-8879

Fax: (886) 2-8732-8870

E-mail: [gennum-taiwan@gennum.com](mailto:gennum-taiwan@gennum.com)

### GERMANY

Hainbuchenstraße 2  
80935 Muenchen (Munich), Germany

Phone: +49-89-35831696

Fax: +49-89-35804653

E-mail: [gennum-germany@gennum.com](mailto:gennum-germany@gennum.com)

### NORTH AMERICA WESTERN REGION

691 South Milpitas Blvd., Suite #200  
Milpitas, CA 95035  
United States

Phone: +1 (408) 934-1301

Fax: +1 (408) 934-1029

E-mail: [naw\\_sales@gennum.com](mailto:naw_sales@gennum.com)

### NORTH AMERICA EASTERN REGION

4281 Harvester Road  
Burlington, Ontario L7L 5M4  
Canada

Phone: +1 (905) 632-2996

Fax: +1 (905) 632-2055

E-mail: [nae\\_sales@gennum.com](mailto:nae_sales@gennum.com)

### KOREA

8F Jinnex Lakeview Bldg.  
65-2, Bangidong, Songpagu  
Seoul, Korea 138-828

Phone: +82-2-414-2991

Fax: +82-2-414-2998

E-mail: [gennum-korea@gennum.com](mailto:gennum-korea@gennum.com)

Gennum Corporation assumes no liability for any errors or omissions in this document, or for the use of the circuits or devices described herein. The sale of the circuit or device described herein does not imply any patent license, and Gennum makes no representation that the circuit or device is free from patent infringement.

All other trademarks mentioned are the properties of their respective owners.

GENNUM and the Gennum logo are registered trademarks of Gennum Corporation.

© Copyright 2009 Gennum Corporation. All rights reserved.

[www.gennum.com](http://www.gennum.com)